



CASE STUDY

CUSTOMER

SYNCRUDE

LOCATION

FT. MCMURRAY, AB CANADA / JAN 2006

EQUIPMENT

793B TRANSMISSION

APPLICATION

TRANSMISSION FLUID

PROVEN RESULTS



PROTECTED TRANSMISSION AND COMPONENTS FROM WEARING

CHALLENGE

Increase of ferrous contamination in the transmission fluids.

SOLUTION

Replace OEM ceramic magnetic filters with OEI magnetic filter elements.

RESULTS

After 500 hours, a substantial amount of ferrous contamination was extracted and trapped on the OEI magnetic filter. If left in the fluid these metal particles will prematurely wear the transmission components and degrade the fluid viscosity.



PRODUCT RECOMMENDATION

MAGNETIC FILTER ELEMENT



403.242.4221



QUOTES@ONEEYEINDUSTRIES.COM

