



CASE STUDY

CUSTOMER

PT. JPAFA COMFEED: FEED MILL

LOCATION

EAST JAVA, INDONESIA / JUL 2012 - OCT 2013

EQUIPMENT

BEAN PROCESSING LINE

APPLICATION

PROCESSED BEAN PRODUCT

PROVEN RESULTS



REDUCED
MAINTENANCE
COSTS
AND LESS
LOST REVENUE
DUE TO
DOWNTIME

“I am so impressed with the performance and results of the magnetic filter compared to our previous magnetic filtration technology, we're changing out all our existing filtration units in exchange for OEI magnetic filtration products.”

- Maintenance Manager

CHALLENGE

Replace existing magnetic filtration that was unable to capture the ferrous contamination and large processing parts that were damaging equipment downline and reducing final product quality.

SOLUTION

Install an OEI Magnetic Filter Element in place of the existing magnetic filtration at the start of the product line.

RESULTS

The photos show large amounts of ferrous and non-ferrous contamination captured by OEI's magnetic filter element. By removing this contamination prior to it reaching components downline, the company increased uptime, reduced maintenance costs, and realized an improvement in product quality.

The filter has been successfully in service for 7 years.



PRODUCT
RECOMMENDATION
**MAGNETIC FILTER
ELEMENT**



403.242.4221



QUOTES@ONEEYEINDUSTRIES.COM

