



CASE STUDY

CUSTOMER

DANIELI CORPORATION

LOCATION

ITALY / MAR 2009

EQUIPMENT

CUTTING OIL FILTRATION SYSTEM

APPLICATION

CUTTING COOLANT

PROVEN RESULTS



DECREASED MAINTENANCE COSTS

“ We are very happy with the results and are viewing the Udine plant to decide how many OEI scrubbers will be needed.”

-Danieli Corporation Representative

CHALLENGE

The traditional filtration system was not cleaning the fluid efficiently thereby reducing the fluid life, prematurely wearing the tools and reducing production.

SOLUTION

Renox the Italian distributor for OEI recommended the installation of an OEI 5000 Series magnetic scrubber.

RESULTS

The OEI 24” scrubber was installed after the cutting oil filtration system and after only a few days of production you can see the metal collected by the scrubber.



PRODUCT RECOMMENDATION
MAGNETIC FILTER SCRUBBER



403.242.4221



QUOTES@ONEEYEINDUSTRIES.COM

